

Main Underground Cable Bank, MH-1 to Auxiliary Building



Omaha Public Power District

OPPD



Field Report

To: Keith Kirchner, Pat Poepsel, Rick Niedergeses		
From: Steve Olson	Project	OPPD FCS 2011 Flood Inundation Structure Assessment OPPD Plant, Ft. Calhoun, NE
CC: Project File, David Rohan	HDR Project No:	164565, Dept. 134
Date: Thursday, Sept 8, 2011	Field Report No:	FR-021
RE: Site Field Observation		

Team Members:

Nick Lampe (HDR), Rich Madson (HDR), Steve Olson (HDR)

Field Activity Objective:

Observe Site Area outside of the Protected Area (PA) for visible signs of flood damage or any indications of possible flood damages that will need to be further evaluated and/or monitored. Priorities were site security fencing, structures, and known utility alignments. (Note that the [REDACTED] were inspected by Team 2 on 09/07/2011.)

Activities Conducted:

Visual observation of exterior site surface areas that were subject to flood waters during the course of the 2011 Missouri River Flood. Relative support strength of the soils along the routes were probed to check relative soil density. Areas of abnormality or concern were noted.

Data Obtained:

Documentation

Documentation includes primarily field notes. However, several site photos were obtained on 09/09/2011 when OPPD personnel were available to take site photos as requested.

Visual and Photography

Visual observation and photos of pertinent items of interest were made. Photos were taken by OPPD personnel escorting the inspection team.

Discussions

Technology

Other

HDR Engineering, Inc.

8404 Indian Hills Drive
Omaha, NE 68114 - 4098

Phone (402) 399-1000
Fax (402) 399-4979
www.hdrinc.com

Page 1 of 2

3253

OPPD00001256

Observations:

[REDACTED]