

Selected Photographs – Apparent Soil Piping and Settlement and Soft Soil/Possible Piping

Photo #	Photo Description (original photograph name)	Page #
Photo 1	Differential settlement of pad-mounted transformer on the south side of Power Lane near the Training Center. Piping evident at the northwest corner of the concrete pad foundation (20110830 PowerLane (1).JPG).	P-4
Photo 2	Piping/soil settlement at base of light pole and street sign located on the south side of Power Lane about 150 feet west of the [REDACTED] (20110830 PowerLane (3).JPG).	P-4
Photo 3	Piping features at the underground electric manhole located on the south side of Power Lane about 50 to 75 feet west of the [REDACTED] (20110830 PowerLane (5).JPG).	P-5
Photo 4	Apparently subsided soil area just south of Power Lane and in alignment with piping at electric manhole referenced in Photo 3. The alignment is believed coincident with underlying utility (electric and/or communication cable) trench (20110830 PowerLane (6).JPG).	P-5
Photo 5	Piping/subsidence feature located at the southwest corner of Power Lane and the driveway entrance to the Technical Center and Administrative Building parking lots (20110830 PowerLane (11).JPG).	P-6
Photo 6	Piping/settlement at base of stop sign located at the southwest corner of Power Lane and the driveway entrance to the Technical Center and Administrative Building parking lots (20110830 PowerLane (12).JPG).	P-6
Photo 7	Piping feature on the north side of the sidewalk located along the south side of the Administrative Building. The feature is coincident with a potable water feed into the building (20110901 AdminBldg (32).JPG).	P-7
Photo 8	Piping feature on the south side of a pad-mounted transformer located just south of the Administrative Building. The feature is in general alignment with the piping feature referenced in Photo 7 and may be coincident with the potable water feed or underground electric lines associated with the transformer (20110901 AdminBldg (39).JPG).	P-7
Photo 9	Piping feature at a sprinkler head in the grass area located on the west side of the Administrative Building (20110901 AdminBldg (44).JPG).	P-8
Photo 10	Piping adjacent to the sidewalk near the northwest corner of the Administrative Building (20110901 AdminBldg (46).JPG).	P-8
Photo 11	Piping adjacent to the sidewalk near the northwest corner of the Administrative Building (20110901 AdminBldg (47).JPG).	P-9
Photo 12	Piping adjacent to the sidewalk near the northwest corner of the Administrative Building (20110901 AdminBldg (48).JPG).	P-9
Photo 13	Piping adjacent to the sidewalk near the northwest corner of the Administrative Building (20110901 PowerLane and UGUtilities (49).JPG).	P-10
Photo 14	Piping/settlement feature on the south side of Power Lane near the southwest corner of the PA. Feature appears coincident with underground electric power utilities. Pavement settlement observed in the Administrative Building parking lot located just south (20110901 PowerLane and UGUtilities (1).JPG).	P-10
Photo 15	Piping/settlement feature on the north side of Power Lane at the light pole located near the southwest corner of the PA. Feature appears coincident with underground electric power utilities (20110909 HighMastLgt & Vicinity (5).JPG).	P-11
Photo 16	Piping/settlement feature on the north side of Power Lane at the light pole located near the southwest corner of the PA. Feature appears coincident with underground electric power utilities (20110909 HighMastLgt & Vicinity (6).JPG).	P-11
Photo 17	Soft soils on the north side of Power Lane. Area appears coincident with underground utilities (20110909 HighMastLgt & Vicinity (10).JPG).	P-12
Photo 18	Soft soils on the north side of Power Lane. Area appears coincident with underground utilities (20110909 HighMastLgt & Vicinity (11).JPG).	P-12
Photo 19	Piping at sanitary sewer Manhole MH-1 located near the southwest corner of the PA, adjacent to the outer security fence. (20110909 HighMastLgt & Vicinity (11).JPG).	P-13
Photo 20	Piping at sanitary sewer Manhole MH-1 located near the southwest corner of the PA, adjacent to the outer security fence. (20110909 InteriorFences&PA (5).JPG).	P-13
Photo 21	Piping feature at Gate 4 of the PA. Feature is adjacent to the south gate post and electric power stub-up (20110909 InteriorFences&PA (7).JPG).	P-14
Photo 22	Piping feature at Gate 4 of the PA. Feature is adjacent to the south gate post and electric power stub-up (20110909 InteriorFences&PA (73).JPG).	P-14

Photo 23	Piping feature at Gate 4 of the PA. Feature is adjacent to the south gate post and electric power stub-up. (20110909_InteriorFences&PA (74).JPG).	P-15
Photo 24	Piping feature inside the PA near the northwest corner of the Radioactive Waste Building. Feature appears coincident with underground pipes of the Fire Protection System. (20110909_InteriorFences&PA (75).JPG).	P-15
Photo 25	Piping feature inside the PA near the northwest corner of the Radioactive Waste Building. Feature appears coincident with underground pipes of the Fire Protection System. (20110909_InteriorFences&PA (84).JPG).	P-16
Photo 26	Soft soil and possible piping/settlement feature adjacent to the west side of the Underground Cable Trench (TRENWA, Inc.), just south of Manhole MH-29 near the north portion of the Old Warehouse and the Fabrication Shop (20110909_Trenwa_SecurityFence_Inspection (16).JPG).	P-16
Photo 27	Soft soil and possible piping/settlement feature adjacent to the west side of the Underground Cable Trench (TRENWA, Inc.), just south of Manhole MH-29 near the north portion of the Old Warehouse and the Fabrication Shop (20110909_Trenwa_SecurityFence_Inspection (17).JPG).	P-17
Photo 28	Soft soil and possible piping adjacent to the east side of the Underground Cable Trench (TRENWA, Inc.) at MH-29 (20110909_Trenwa_SecurityFence_Inspection (21).JPG).	P-17
Photo 29	Soft soil and possible piping adjacent to the east side of the Underground Cable Trench (TRENWA, Inc.) at MH-29 (20110909_Trenwa_SecurityFence_Inspection (22).JPG).	P-18
Photo 30	Soft soil and possible piping adjacent to the east side of the Underground Cable Trench (TRENWA, Inc.) at MH-29 (20110909_Trenwa_SecurityFence_Inspection (23).JPG).	P-18
Photo 31	Soft soil and possible piping at the camera tower/high mast lighting pad located at the northwest corner of the PA (20110909_Trenwa_SecurityFence_Inspection (55).JPG).	P-19
Photo 32	Soft soil and possible piping at the camera tower/high mast lighting pad located at the northwest corner of the PA (20110909_Trenwa_SecurityFence_Inspection (57).JPG).	P-19
Photo 33	Soft soil and piping feature adjacent to hand probe in concrete sidewalk between security fences along the north side of the ISFSI (20110909_Trenwa_SecurityFence_Inspection (59).JPG).	P-20
Photo 34	Soft soil and piping feature adjacent to hand probe in concrete sidewalk between security fences along the north side of the ISFSI (20110909_Trenwa_SecurityFence_Inspection (60).JPG).	P-20
Photo 35	Soft soil and possible piping at the camera tower/high mast lighting pad located near the northeast corner of the ISFSI (20110909_Trenwa_SecurityFence_Inspection (68).JPG).	P-21
Photo 36	Soft soil and possible piping at the camera tower/high mast lighting pad located near the northeast corner of the ISFSI (20110909_Trenwa_SecurityFence_Inspection (69).JPG).	P-21
Photo 37	Soft soil/piping features located adjacent to the east side of the Underground Cable Trench (TRENWA, Inc.) west of [REDACTED] (20110909_Trenwa_SecurityFence_Inspection (73).JPG).	P-22
Photo 38	Soft soil/piping feature located adjacent to the east side of the Underground Cable Trench (TRENWA, Inc.) west of [REDACTED] (20110909_Trenwa_SecurityFence_Inspection (75).JPG).	P-22
Photo 39	Soft soil/piping feature located adjacent to the north side of the Underground Cable Trench (TRENWA, Inc.) south of the Radioactive Waste Building and southeast of [REDACTED] (20110909_Trenwa_SecurityFence_Inspection (85).JPG).	P-23
Photo 40	Soft soil/piping feature located adjacent to the north side of the Underground Cable Trench (TRENWA, Inc.) south of the Auxillary Building (20110909_Trenwa_SecurityFence_Inspection (86).JPG).	P-23
Photo 41	Piping adjacent to the Underground Cable Trench (TRENWA, Inc.) and possible top panel movement located west of the Security Building (20110909_Trenwa_SecurityFence_Inspection (90).JPG).	P-24
Photo 42	Piping adjacent to the Underground Cable Trench (TRENWA, Inc.) and possible top panel movement located west of the Security Building (20110909_Trenwa_SecurityFence_Inspection (91).JPG).	P-24
Photo 43	Apparent piping feature at isolation valve DW 542 of the Blair Water System located just north of Power Lane and the Training Center (20110913_Waterline (5).JPG).	P-25
Photo 44	Soft soil/piping and apparent soil settlement at isolation valve DW 541 of the Blair Water System located just north of Power Lane and the Training Center (20110913_Waterline (9).JPG).	P-25

Photo 45	Soft soil/piping and apparent soil settlement at isolation valve DW 541 of the Blair Water System located just north of Power Lane and the Training Center (20110913_Waterline_(10).JPG).	P-26
Photo 46	Soft soil/piping and apparent soil settlement at isolation valve DW 541 of the Blair Water System located just north of Power Lane and the Training Center (20110913_Waterline_(12).JPG).	P-26
Photo 47	Piping feature/sand boil (about 1 foot deep, 3.5 feet in diameter) in the Missile Shield Room on the south side of the Auxiliary Building (20110914_AuxBldg_AirPlenum&Blastwall Interior_(1).JPG).	P-27
Photo 48	Piping feature/sand boil (about 1 foot deep, 3.5 feet in diameter) in the Missile Shield Room on the south side of the Auxiliary Building (20110914_AuxBldg_AirPlenum&Blastwall Interior_(2).JPG).	P-27
Photo 49	Piping feature/sand boil (about 1 foot deep, 3.5 feet in diameter) in the Missile Shield Room on the south side of the Auxiliary Building (20110914_AuxBldg_AirPlenum&Blastwall Interior_(3).JPG).	P-28
Photo 50	Piping feature/sand boil (about 1 foot deep, 3.5 feet in diameter) in the Missile Shield Room on the south side of the Auxiliary Building (20110914_AuxBldg_AirPlenum&Blastwall Interior_(4).JPG).	P-28
Photo 51	High water mark on Missile Shield Room wall indicating about 9 inches of water was piped into the room (20110914_AuxBldg_AirPlenum&Blastwall Interior_(8).JPG).	P-29
Photo 52	Thin (about 1/16-inch thick) layer of sediment apparently piped into the room (20110914_AuxBldg_AirPlenum&Blastwall Interior_(10).JPG).	P-29