

Photo 47 – Piping feature/sand boil (about 1 foot deep, 3.5 feet in diameter) in the Missile Shield Room on the south side of the Auxiliary Building.



Photo 48 – Piping feature/sand boil (about 1 foot deep, 3.5 feet in diameter) in the Missile Shield Room on the south side of the Auxiliary Building.




Photo 49 - Piping feature/sand boil (about 1 foot deep, 3.5 feet in diameter) in the Missile Shield Room on the south side of the Auxiliary Building.



Photo 50 - Piping feature/sand boil (about 1 foot deep, 3.5 feet in diameter) in the Missile Shield Room on the south side of the Auxiliary Building.





Photo 51 – High water mark on Missile Shield Room wall indicating about 9 inches of water was piped into the room.



Photo 52 – Thin (about 1/16-inch thick) layer of sediment apparently piped into the room.