



- NOTES:
- STRUCTURE HEIGHTS SHOWN ARE CONCEPTUAL AND DRAWING IS NOT TO SCALE.
 - VIBROFLOTATION TEST BORINGS FROM OPPD FILE #'S 008494, 015873 AND 015874 WERE COMPARED TO DRAWINGS 11405-S-1 (116380), 11405-S-272 (116504) AND 11405-S-273 (116505).

± GROUND WATER ELEVATION 12-10-2010
 □ GROUND WATER ELEVATION 6-3-2011
 □ ODOLYTIC LIMESTONE
 □ FINE GRAINED LIMESTONE



Section B-B
 Fort Calhoun Station

Plant and Facility Geotechnical
 and Structural Assessment

DATE
 August 2012

FIGURE
 Figure 2-3

